

AMERICAN CONSULTING

Architects Consultants Engineers 7260 SHADELAND STATION INDIANAPOLIS, IN 46256-3957 PHONE (317) 547-5580 WWW.AMERCONS.COM

Structures and Debris to be Removed

US Steel WWTP Demolition Portage, Porter County, Indiana

May 20, 2005



Photo 1: Data Point 1-Fire Hydrant 1



Photo 2: Data Point 2-Manhole



Photo 3: Data Point 3-Lan-Sat Marker



Photo 4: Data Point 4-Effluent Building



Photo 5: Data Point 5-Light Pole



Photo 6: Data Point 6-Vault



Photo 7: Data Point 7-Fire Hydrant 2



Photo 8: Data Point 8-Concrete Barrier



Photo 9: Data Point 8-Concrete Barrier



Photo 10: Data Point 9-Digester Tank 1



Photo 11: Data Point 10-Digester Tank 2



Photo 12: Data Point 11- Secondary Clarifier



Photo 13: Data Point 12-Secondary Clarifier



Photo 14: Data Point 12-Chlorine Contact Tank



Photo 15: Data Point 13-Aeration Basin



Photo 16: Data Point 14-Tank



Photo 17: Data Point 15-Abandoned Valve Vault



Photo 18: Data Point 16-Debris and Timber



Photo 19: Data Point 17-Pipe Bridge



Photo 20: Data Point 17-Pipe Bridge



Photo 21: Data Point 17-Pipe Bridge



Photo 22: Data Point 17-Pipe Bridge



Photo 23: Data Point 18-Monitoring Station, East Side of Burns Ditch



Photo 24: Data Point 19-Concrete Debris to be Removed



Photo 25: Data Point 20-Debris to be Removed



Photo 26: Data Point 21-Debris to be Removed



Photo 27: Data Point 21-Debris to be Removed



Photo 28: Data Point 22-Debris to be Removed



Photo 29: Data Point 23-Debris to be Removed



Photo 30: Data Point 23-Debris to be Removed



Photo 31: Data Point 24-Debris to be Removed



Photo 32: Data Point 25-Debris to be Removed



Photo 33: Debris to be Removed



Photo 34: North Fence Line



Photo 35: North Fence Line



Photo 36: East Fence Line



Photo 37: West Fence Line



Photo 38: West Fence Line



Photo 39: West Side WWTP



Photo 40: North Side WWTP



Photo 41: Data Point 23-East Side WWTP




Photo 42: Chlorine Building, South Side WWTP



Photo 43: Looking South along Burns Ditch from Pipe Bridge



Photo 45: Monitoring Station, west side of Burns Ditch




Photo 47: Outfall, west side of Burns Ditch



Photo 44: Looking North along Burns Ditch from Pipe Bridge



Photo 46: Monitoring Station under Pipe Bridge



Photo 48: Debris to be removed



Photo 49: Debris to be removed



Photo 50: Access Gate (Not to be Removed)